

Crankpin and main bearing journal diameter machining

QUALITY PROCEDURES

OSM WI/001

CRANKPIN JOURNAL MACHINING

Typical Workscope

- 1. Visual inspection of condition of fillet radii.
- 2. Concentricity checks from journal to radii using dial indicator.
- Surface hardness tests of crankpin journal at one inch intervals every 45 and plot results.
- 4. Plug oil feed holes to prevent ingress of foreign particles.
- 5. Hand dress hardspots to establish depth.
- Dimensional check and record.
- 7. Consult with customer to establish target final dimensions to suit available bearings,
- 8. Assemble crankpin machining equipment,
- 9. Set machine concentric and parallel.
- 10. Take proving cut to clean up damaged surface,
- 11. Repeat surface hardness tests.
- 12. Crack detection test of surface by magnetic particle inspection.
- 13. Dimensional checks.
- 14. Consult with customer.
- 15. Machine to full journal to agreed size plus polishing allowance.
- 16. Final surface hardness test.
- 17. Final crack detection test.
- 18. Blend radii to re-establish form.
- 19. Polish radii and oil holes.
- Hone and polish journal to finished size. Checking for:

Straightness using straight edge and engineers blue.

- Ovality and parallelism using micrometer.
- 21. Final inspection.
- 22. Remove plugs in oil feed holes.
- 23. Provide customer with copies of inspection reports.
- 24. Clean work are a.

APPROVED BY				DATE	20 th December 2001		
ISSUE	1	2	3	4	5	6	7
DATE	Sept 93	Nov 93	April 97	Dec 01			





Setting a false ring to re-machine the fillet radi











Re machining fillet radi



















Re machining hard bearing journal diameter











Superfinishing journal diameter



